

FIG. 1




FIG. 1




FIG. 2




FIG. 3




FIG. 4

FIG. 5




FIG. 6




FIG. 7





FIG. 8






FIG. 9




FIG. 10




FIG. 11




FIG. 12

FIG. 13

300




FIG. 13

300



FIG. 14

300

FIG. 15

300





FIG. 16



[Faint, illegible handwritten notes]






Fig. 18



17

19. 16.

0943064-003404
TORCRO-490CH660



F 16. 20

09943064.003404
125




FIG: 21




FIG. 22







FIG. 23

FIG. 23







FIG. 27






FIG. 29






FIG. 30

FIG. 31



1500




FIG. 33




FIG. 34

FIG. 35




FIG. 36




FIG. 37

FIG. 38

FIG. 39

2200




FIG. 40

2300




FIG. 41

FIG. 43




FIG. 43




FIG. 45




FIG. 44




FIG. 42

2800




FIG. 46

DATE 11-30-1960

2900
✓




FIG. 47




FIG. 48




FIG. 49

00943054 003404




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58





FIG. 59.



00043064 083104




FIG. 61

FIG. 62

3200
4




FIG. 62